



Photo 1 – Choquette Dairy, 246 Choquette Road, Enosburg Falls, VT – 08/03/16
Stationary tanker truck for whey storage.



Photo 2 – Choquette Dairy, 246 Choquette Road, Enosburg Falls, VT – 08/03/16
Overflow pipe from the liquid whey tank truck to the manure pit.




Photo 3 – Choquette Dairy, 246 Choquette Road, Enosburg Falls, VT – 08/03/16
Some white/gray deposition on a grassy slope from the whey tank truck to the small stream below.



Photo 4 – Choquette Dairy, 246 Choquette Road, Enosburg Falls, VT – 08/03/16
Small stream located downgradient of the liquid whey tank.



Photo 5 – Choquette Dairy, 246 Choquette Road, Enosburg Falls, VT – 08/03/16
Spoiled feed pile on the edge of a silage bunker pad.



Photo 6 – Choquette Dairy, 246 Choquette Road, Enosburg Falls, VT – 08/03/16
Location where the drain pipe (in photo #5) daylights into a grassy drainage ditch.